Approved For Release 2001/03/02 : CIA-RDP78-04993A000100060002-0

				A 1 3		25X1A6a	
	VIA TR (Specify Air	or Sea Pouch)	CONFIDENTI	AL' DISPATCH	ΝО	-	
	·		SECRET		8 f NGV 198	57	
		ef, FE	7	DATE		····	
	ATTN FROM : Chie		7			25X1A6a	
	SUBJECT	SUBJECT Support/Administrative SPECIFIC - Dehumidified Warehouse - Building #1104					
	ACTION REQUI	RED: For infe	ormation only				
					25X1A		
25X1A	1. Pri	or to his depart	arture from Headquar				
	was requested by RE&C Division representatives to submit certain information concerning the dehumidified warehouse, 7. C/REC Building #1104. This information is as follows: DC/REC						
	a.	Normal humid:	ity maintained?		(C/ACQ	
		141%			r:	C/C.E.	
	b∙	Number of un	its installed?			C/U.E. 1400(11/20)	
		One				REPORT	
	C.	Catalog No.	of unit?				
•		DOR 1050 - Do	esomatic Products Ir	nc.		160	
	đ∙	Number of un	its required for nor	rmal operation?	,	1835.	
		One		•	•	FILE (roturn)-	
		Average or appearating condi-	oproximate time requ tions?	ired to lower	warehouse i	onstr	
	prohibit on		ntents and high outs The unit is in co			3) 25X1A6a	
Do	cument No. 12		_1	f. Period of	regenerati	ion/	
	Change In Class.		VEIDENITIAL	1	_	7	
Cla	Declassified ss. Changed To: 7	s sec	SECTATE OF		RECORDED L REGISTRY		
Auf Dat	th.: HR 70-2	or Release 22	O CASTAGRATION O	i	100060002	-0	
	1UN +040 51-2	8	THE COPY		-1-4		

Approved For Release 2001/03/02 : CIA-RDP78-04683A000100060002-0

SECRET

25X1A6a

5 November 1957 Page 2

8 NOV 1957.

- f. Period of regeneration for unit?70 minutes maximum capacity.
- g. Approximate power required for operation of unit?

 Connected full load is 34 K.W.
- h. Cost of installation?
 \$10,200 paid by contractor for the unit.
- i. Operating difficulties or problems?

Excellent results have been obtained with this unit. We have experienced no mechanical trouble. Maintenance is easily applied and minor electrical difficulties are our only problems.

j. Miscellaneous comments:

It is recommended that for future installations the unit be isolated from the general storage area by partitioning of grillwork, hardware cloth, etc. Adequate lighting (permanent wall fixtures) for servicing such units would be advantageous.

2. Additional information will be provided upon request.



25X1A9a

5 November 1957

Distribution:

2 - Chief, FE

3 - RE&C,OL

CONFIDENTIAL